Nissan Consult3(SP38-B) Installation Step and Registeration Step

Firstly,install consult III step.exe





Consult-III_V9.21.01.00.00_setup
File Edit View Favorites Tools Help
Back Search Folders
Address G:\Consult-III_V9.21.01.00.00_setup
Go
CD Writing Tasks
Write these files to CD
File and Folder Tasks
Rename this file
Move this file
Copy this file
Publish this file to the Web
E-mail this file
Delete this file
Other Places
□□ (G:)
My Documents
Shared Documents
My Network Places
Details
Files Currently on the CD
Bluetooth driver
dotnetfx1v...
dotnetfx.exe
Setup.Ini
Setup - Nissan Consult III (AVTOTOOLS)
Select Destination Location
Where should Nissan Consult III (AVTOTOOLS) be installed?
Setup will install Nissan Consult III (AVTOTOOLS) into the following folder.
To continue, click Next. If you would like to select a different folder, click Browse.
Files\Nissan North America\CONSULT-III Registration and License
Browse...
At least 362.9 MB of free disk space is required.
< Back
Next >
Cancel


Description: Nissan Consult III (AVTOTOOLS) Setup File Version: 0.0.0.0 Date Created: 4/24/2011 8:32 PM Size: 342 MB
Start
Consult-III_V9.21.01.00...
2.JPG - Paint
Setup
2:15 PM
Consult-III_V9.21.01.00.00_setup
File Edit View Favorites Tools Help
Back Search Folders
Address G:\Consult-III_V9.21.01.00.00_setup
Go
CD Writing Tasks
Write these files to CD
File and Folder Tasks
Rename this file
Move this file
Copy this file
Publish this file to the Web
E-mail this file
Delete this file
Other Places
□□ (G:)
My Documents
Shared Documents
My Network Places
Details
Files Currently on the CD
Bluetooth driver
dotnetfx1v...
dotnetfx.exe
Setup.Ini
Setup - Nissan Consult III (AVTOTOOLS)
Ready to Install
Setup is now ready to begin installing Nissan Consult III (AVTOTOOLS) on your computer.
Click Install to continue with the installation, or click Back if you want to review or change any settings.
Destination location:
C:\Program Files\Nissan North America\CONSULT-III Registration and License
< Back
Install
Cancel

Description: Nissan Consult III (AVTOTOOLS) Setup File Version: 0.0.0.0 Date Created: 4/24/2011 8:32 PM Size: 342 MB
Start
Consult-III_V9.21.01.00...
3.JPG - Paint
Setup
2:15 PM


Consult-III_V9.21.01.00.00_setup
File Edit View Favorites Tools Help
Back Search Folders
Address G:\Consult-III_V9.21.01.00.00_setup
Go
CD Writing Tasks
Write these files to CD
File and Folder Tasks
Rename this file
Move this file
Copy this file
Publish this file to the Web
E-mail this file
Delete this file
Other Places
□□ (G:)
My Documents
Shared Documents
My Network Places
Details
Files Currently on the CD
Bluetooth driver
dotnetfx1v...
dotnetfx.exe
Setup.Ini
Setup - Nissan Consult III (AVTOTOOLS)
Installing
Please wait while Setup installs Nissan Consult III (AVTOTOOLS) on your computer.
Extracting files...
C:\...\Nissan North America\CONSULT-III Registration and License\data2.cab
Cancel


Description: Nissan Consult III (AVTOTOOLS) Setup File Version: 0.0.0.0 Date Created: 4/24/2011 8:32 PM Size: 342 MB
Start
Consult-III_V9.21.01.00...
4.JPG - Paint
Setup
2:17 PM
Consult-III_V9.21.01.00.00_setup
File Edit View Favorites Tools Help
Back Search Folders
Address G:\Consult-III_V9.21.01.00.00_setup
Go
CD Writing Tasks
Write these files to CD
File and Folder Tasks
Rename this file
Move this file
Copy this file
Publish this file to the Web
E-mail this file
Delete this file
Other Places
□□ (G:)
My Documents
Shared Documents
My Network Places
Details
Files Currently on the CD
Bluetooth driver
dotnetfx1v...
dotnetfx.exe
Setup.Ini
Installing
Please wait while Setup installs Nissan Consult III (AVTOTOOLS) on your computer.
Finishing installation...
InstallShield Wizard
Consult-III Setup is preparing the InstallShield Wizard, which will guide you through the rest of the setup process. Please wait.
Cancel

Description: Nissan Consult III (AVTOTOOLS) Setup File Version: 0.0.0.0 Date Created: 4/24/2011 8:32 PM Size: 342 MB
Start
Consult-III_V9.21.01.0...
5.JPG - Paint
Setup
2:17 PM


Consult-III 09.21.01.00.00 : First Installation
Consult-III V09.21.01.00.00
Consult-III 09.21.01.00.00 : First Installation
License Agreement
Please read the following license agreement carefully.
This software is a diagnostic application (please do not install it on PCs other than those that are specifically designated).
For those PCs other than those that are specifically designated, the software may not be installed properly, or it may cause damage to the main body of the PC or the data that is stored.
The content of this software is copyright-protected.
All or a part of the content of this software other than for the purpose described above shall not be permitted to duplicate, reprint, screen, publicly transmit (including transmission-enabling for automatic public transmission), lend, translate or make alterations, etc. regardless of its media format without prior permission by Nissan Motor Co., Ltd.
Furthermore any actions other than those that are written in the contract that was stipulated during its purchase are strictly prohibited.
Actions that deviate from the uses written above will be subject to the compensation damage from a civil case, and/or a criminal penalty.
I accept the terms of the license agreement
I do not accept the terms of the license agreement
Print
InstallShield
< Back
Next >
Cancel
Start
Consult-III_V9.21.01.0...
6.JPG - Paint
Setup
Consult-III 09.21.01....
2:18 PM


Consult-III 09.21.01.00.00 : First Installation
Consult-III V09.21.01.00.00
Consult-III 09.21.01.00.00 : First Installation
Select your market.
DOMESTIC MARKET (DOM)
NORTHAMERICA MARKET (NAM)
EUROPE MARKET (EUR)
GLOBAL MARKET (GOM)
InstallShield
< Back
Next >
Cancel
Start
Consult-III_V9.21.01.0...
7.JPG - Paint
Setup
Consult-III 09.21.01....
2:23 PM


Consult-III 09.21.01.00.00 : First Installation
Consult-III V09.21.01.00.00
Consult-III 09.21.01.00.00 : First Installation
Select your area.
North America
InstallShield
< Back
Next >
Cancel
Start
Consult-III_V9.21.01.0...
8.JPG - Paint
Setup
Consult-III 09.21.01....
2:24 PM


Consult-III 09.21.01.00.00 : First Installation
Consult-III V09.21.01.00.00
Consult-III 09.21.01.00.00 : First Installation
Select your country.
American Samoa
Canada
Guam
Hawaii
Saipan
Tinian Island
U.S.A.
North America Common
Puerto Rico
InstallShield
< Back
Next >
Cancel
Start
Consult-III_V9.21.01.0...
9.JPG - Paint
Setup
Consult-III 09.21.01....
2:24 PM


Consult-III 09.21.01.00.00 : First Installation
Consult-III V09.21.01.00.00
Consult-III 09.21.01.00.00 : First Installation
Select the application language.
English
Finnish
French
German
Greek
Italian
Japanese
Spanish
Chinese(Traditional)
Chinese(Simplified)
Russian
InstallShield
< Back
Next >
Cancel
Start
Consult-III_V9.21.01.0...
10.JPG - Paint
Setup
Consult-III 09.21.01....
2:25 PM


Consult-III 09.21.01.00.00 : First Installation
Consult-III V09.21.01.00.00
Consult-III 09.21.01.00.00 : First Installation
Start Copying Files
Review settings before copying files.
Setup has enough information to start copying the program files. If you want to review or change any settings, click Back. If you are satisfied with the settings, click Next to begin copying files.
Current Settings:
Market: NORTHAMERICA MARKET (NAM)
Area: North America
Country: U.S.A.
Language: English
InstallShield
< Back
Next >
Cancel
Start
Consult-III_V9.21.01.0...
11.JPG - Paint
Setup
Consult-III 09.21.01....
2:25 PM


Consult-III 09.21.01.00.00 : First Installation
Consult-III V09.21.01.00.00
Consult-III 09.21.01.00.00 : First Installation
Setup Status
The installation is installing the CONSULT-III.
Installing
C:\ConsultIII\DiagnosticData\Display\FGKAIRBAG.xml
InstallShield
Cancel
Start
Consult-III_V9.21.01.0...
12.JPG - Paint
Setup
Consult-III 09.21.01....
2:26 PM


Consult-III 09.21.01.00.00 : First Installation
Consult-III V09.21.01.00.00
Consult-III 09.21.01.00.00 : First Installation
First Installation
The installation of CONSULT-III software succeeded.
InstallShield
< Back
Finish
Cancel
Start
Consult-III_V9.21.01.0...
13.JPG - Paint
Setup
Consult-III 09.21.01....
2:27 PM



Secondly,Found New Hardware




Found New Hardware Wizard
Welcome to the Found New Hardware Wizard
Windows will search for current and updated software by looking on your computer, on the hardware installation CD, or on the Windows Update Web site (with your permission).
Read our privacy policy
Can Windows connect to Windows Update to search for software?
Yes, this time only
Yes, now and every time I connect a device
No, not this time
Click Next to continue.
< Back
Next >
Cancel
UltraEdit
UltraISO
NetWaiting
UltraCompare Professional
Start
15.JPG - Paint
Found New Hardware ...
2:31 PM


Found New Hardware Wizard
This wizard helps you install software for:
JCI-1B-Alliance Vehicule Interface
If your hardware came with an installation CD or floppy disk, insert it now.
What do you want the wizard to do?
Install the software automatically (Recommended)
Install from a list or specific location (Advanced)
Click Next to continue.
< Back
Next >
Cancel
UltraEdit
UltraISO
NetWaiting
UltraCompare Professional
Start
16.JPG - Paint
Found New Hardware ...
2:32 PM





Thirdly, VI Selection Steps


CONSULT-III
14:34
VIMI Selection (VI Selection)
Selected VI Name
Error
There are no registered VI/MI. Please contact your administrator.
OK
MI Select
Connect
Connect to the VI defined as default
Start
20.JPG - Paint
CONSULT-III
2:34 PM


CONSULT-III
14:35
SUB
Sub mode
VIMI Selection (VI Selection)
Selected VI Name
Selected MI Name
Detected VI list
MI Select
Connect
Connect to the VI defined as default
Start
22.JPG - Paint
CONSULT-III
2:35 PM





Input Password: “nissanconsult3”


CONSULT-III
14:36
CONSULT-III
14:37
SUB
Administrator Menu
VIMI Registration
VIMI Configuration
Hidden Mode
CONSULT-III
14:38
SUB
VIMI Registration
VI serial Number
926573
MI serial Number
CLEAR
Set
VI list
MI list
Delete
Export
Import
Start
25.JPG - Paint
CONSULT-III
2:38 PM


CONSULT-III
14:39
VIMI Registration
VI serial Number
MI serial Number
CLEAR
Set
VI list
MI list
926573
Delete
Export
Import
Start
26.JPG - Paint
CONSULT-III
2:39 PM


CONSULT-III
14:40
VIMI Selection (VI Selection)
Selected VI Name
926573
Selected MI Name
Detected VI list
926573
MI Select
Connect
Connect to the VI defined as default
Start
24.JPG - Paint
CONSULT-III
2:40 PM



Forthly, Vehicle Selection




CONSULT-III
14:43
Vehicle Selection : Confirmation Vehicle
Market Code:
Area Code:
Country Code:
NAM
North America
U.S.A.
VIN :
Vehicle Name
INFINITI FX35/FX45
Model Year :
2003
Change
Confirm
Start
30.JPG - Paint
CONSULT-III
2:43 PM


CONSULT-III
14:44
CAN
DTC
System Scope
Select System Shortcut
System
ENGINE
ABS
METER/M&A
BCM
AIR BAG
ICC/ADAS
HVAC
ENGINE
Start
System Call
81%
Renew
Start
31.JPG - Paint
CONSULT-III
2:44 PM


CONSULT-III
14:44
Work Selection
CAN
SUB
DTC
Diagnosis
To perform diagnosis, touch the button, "Diagnosis".
-CAN Diagnosis
-All DTC Reading
ECU Identification
Self Diagnostic Result
Data Monitor
Active Test
Function Test
DTC & SRT Confirmation
Repair
To perform operation required after parts replacement or key r
egistration etc, touch the button, "Repair".
-System selection
ECU Identification
Work support
Configration
-Reprogramming
-NATS
Start
32.JPG - Paint
CONSULT-III
2:44 PM


CONSULT-III
14:45
All DTC Reading
ENGINE
Select
Store
Print
Expl
FFD
P0115 : ECT SEN/CIRC
P0110 : AIR TEMP SEN/CIRC
P0180 : FUEL TEMP SEN/CIRC
P1490 : VC/V BYPASS/V
P0105 : ABSL PRES SEN/CIRC
P0446 : VENT CONTROL VALVE
P1464 : FUEL LEVL SEN/CIRC
Start
33.JPG - Paint
CONSULT-III
2:45 PM